

q table for significance = 0.05 (confidence = 95%) for small samples

For use with Tukey's Honest Significant Difference Test

Vertical Axis = Denominator Degrees of Freedom

Horizontal Axis = Number of Treatments

df	2	3	4	5	6	7	8	9	10
1	18.0	27.0	32.8	37.2	40.5	43.1	45.4	47.3	49.1
2	6.09	8.33	9.80	10.89	11.73	12.43	13.03	13.54	13.99
3	4.50	5.91	6.83	7.51	8.04	8.47	8.85	9.18	9.46
4	3.93	5.04	5.76	6.29	6.71	7.06	7.35	7.60	7.83
5	3.64	4.60	5.22	5.67	6.03	6.33	6.58	6.80	6.99
9	3.20	3.95	4.42	4.76	5.02	5.24	5.43	5.60	5.74
14	3.03	3.70	4.11	4.41	4.64	4.83	4.99	5.13	5.25
19	2.96	3.59	3.98	4.26	4.47	4.64	4.79	4.92	5.04
24	2.92	3.53	3.90	4.17	4.37	4.54	4.68	4.81	4.92

**Objective Experiments
336 36th Street #179
Bellingham WA 98225**

info@ObjExp.com